





Accelerometer + Magnetometer sensor  
LSM303AGR






Relative humidity and temperature sensor  
HTS221




Pressure sensor  
LPS22HB




Arduino UNO R3 Connectors




I2C grove connector



SWD




Reset Button



RF switch debug header



Debug connect



RF & MCU Power Consumption Measurement

